



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 10

1200 Sixth Avenue, Suite 900
Seattle, Washington 98101-3140

JUL - 7 2015

OFFICE OF
COMPLIANCE AND ENFORCEMENT

Reply to: OCE-101

CERTIFIED MAIL -- RETURN RECEIPT REQUESTED

EPA WARNING LETTER

Mr. Dave Stiner
Director of Facilities
Washington Beef, LLC
201 Elmwood Road
Toppenish, Washington 98948

Re: Inspection of Risk Management Program (RMP)
EPA RMP Facility ID# 1000 0010 7804

Dear Mr. Stiner:

On May 20, 2015, the U.S. Environmental Protection Agency (EPA) conducted an inspection of the Washington Beef, LLC facility located at 201 Elmwood Road, Toppenish, Washington. The purpose of the inspection was to evaluate compliance with Section 112(r) of the Clean Air Act also known as the Risk Management Program (RMP). The RMP inspection was conducted pursuant to the authorities under Section 112(r) and Section 114 of the Clean Air Act. Listed below are the areas of concern identified by EPA:

Hazard Assessment requirements: Washington Beef, LLC failed to use the most recent Census data, or other information to estimate the population as required by 40 C.F.R. § 68.30(c). During the inspection, Washington Beef, LLC used the Census date from 2000 for their January 16, 2013 RMP submission.

Please provide the documentation to substantiate that the areas of concern listed above have been corrected. A copy of the documents must be sent to Javier Morales, RMP Coordinator, within 14 days of your receipt of this letter. The documents may be sent via e-mail, fax or mail.

Javier Morales, RMP Coordinator
U.S. EPA Region 10
1200 Sixth Avenue, Suite 900, OCE-101
Seattle, WA 98101
Fax: 206-553-4743

Please refer to the document *General Risk Management Program Guidance* for additional information pertaining to the areas of concern addressed above. This guidance document can be found on EPA's website at:

http://www.epa.gov/emergencies/content/rmp/rmp_guidance.htm#General

We urge you to take the steps necessary to address these concerns and to ensure that all aspects of your operation are conducted in accordance with all applicable federal, state, and local requirements. If in the future, additional violations are identified and/or corrections to the identified concerns are not made, EPA may proceed with enforcement action.

If you have any questions about the inspection or the Risk Management Program, please contact Javier Morales, RMP Coordinator, at (206) 553-1255 or morales.javier@epa.gov.

Sincerely,



Kelly McFadden, Manager
Pesticides and Toxics Unit